

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

# Causes of Heavy Vehicle Fires

# By Peter Hart Hartwood Consulting Pty Ltd





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Engine compartment fire – Adelaide Hills





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE - 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

### My ordering of the most common causes of fires on trucks:

- 1. Arcs on the starter (or battery cables), alternator, cabin and trailer supply cable.
- 2. Fuel line rubs or failures that result in leaks / sprays of fuel onto the exhaust.
- 3. Lubrication/hydraulic oil line failures near to the exhaust.
- 4. Turbo charger oil seal failures.
- 5. Flammable material resting against the turbo charger or the exhaust.
- 6. Electrical failures from hot terminals causing insulation to burn.
- 7. After-market fuse problems.
- 8. Overloaded minor electrical cables and hot relays.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

### The most common causes of fires on <u>trailers</u> are:

- 1. Wheel bearing failures (or seal failures) that result in dragging (drum) brakes.
- 2. Dragging brakes due to damage to the pneumatic spring brake system.
- 3. Tyres catching fire because they are flat or poorly inflated or rubbing on hard mudguard surfaces.
- 4. Friction rubs on mezzanine support brackets.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences


# Crash on M5 follows earlier truck fire that caused peak hour gridlock

#### By Jenny Noyes

Updated July 31, 2019 – 10.36am, first published at 7.50am



f 🎔 🖻 <u>A</u> A A



#### TODAY'S TOP STORIES

#### CLARENCE STREET ATTACK

'Taken too soon:' Victim remembered as government responds to tragedy 2 hours ago

#### ABORTION

Andrew Constance demands fellow Berejiklian minister 'explain' himself

#### CLARENCE STREET ATTACK

'Sorry a million times': Sister of suspect speaks out

Motorists and commuters on the M5 in Sydney's west have encountered massive delays on Wednesday morning, with a crash now causing westbound headaches after an earlier truck fire resulted in citybound queues of more than 20 kilometres at the height of the morning peak.

Emergency services were initially called about 7am following reports of a prime mover well alight on the M5 near the intersection with the Hume Highway in Casula.



Delays continue. Traffic now back to Denham Court. Northbound traffic on Campbelltown Rd is also heavy and southbound on the M7 getting to the M5.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Rubs on Main Electrical Cables**





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

Fire was caused by the alternator cable running over the engine stud.

The split conduit opened up and let the stud in to rub on the cable.

Sparking ignited the polymer conduit.

This cable had no circuit breaker protection.







A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences



Rasping of the conduit and plastic led to a short-circuit.

This fire occurred inside the battery box.

The sparking ignited the polymer conduit.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



A rub on the positive battery cable at a steel-spined clamp point underneath the cabin.

Sparking on main cable ignited the split-plastic conduit.

This cable had no electrical fuse protection.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The fire appears to have started in the electrical compartment on the firewall underneath the windscreen.

This is not so!






# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The fire started at a minor link cable between the starter motor and the chassis rails.

Because the main return cable had been left off the starter motor when it was changed, starter motor current returned via a minor cable, which overheated.






# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The fire spread from the starter motor region to the cabin electrical installation on the firewall just below the windscreen.

The fire spread via burning conduits.

The plastic conduits provided fuel for the fire and then spread it vertically.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences


### **Faults on Minor Electrical Cables**





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



This fire started in an aftermarket fuse holder





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Carbonate filler comes out of the rubber when it gets hot.

This contaminates the fuse terminals and may result in hot terminals.

Terminal heating = I.I.R








A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



This fire started in a beacon light on a cabin roof.

The rubber pad is used for vibration isolation.

Fires can start at return electrical connections when there is poor clamping force.

Hot terminals result. Plastics catch fire.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

- 1. Poor quality connections cause hot terminals.
- 2. After-market suppliers over-rate electrical terminals. Half the published rating!
- 3. Lack of fire retardancy standards for after-market electrical equipment.
- 4. Lack of electrical protection on add-on wiring.
- 5. Poor quality terminal connections.
- 6. Starter motor return cable left off.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Fuel and Oil Line Fires**





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Only the exhaust and turbocharger are hot enough to ignite oil or diesel fuel.






# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The fire started outside the cabin on the RHS just in front of axle 2





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### Material Choice For Mezzanine Floor Brackets

Fire is caused by hot metal rubbings from the support brackets accumulating on top of vulnerable freight boxes.

Polyamide or polyurethane U-shaped pads are being trialled to prevent metal-metal rubbing.

Sideways movement is needed to avoid stress points in the metal frame.








CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY



A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The fuel lines run down the side of the fuel tank.

They are polyamide hoses with poor mechanical protection (spiral wrap).


A leak from the polyamide return line (smaller line) will cause a fuel spray without any change in engine operation.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences





High pressure engine tube cracks.

The cracking and wearing of tubes is the result of vibration due to pressure pulses in the high pressure fuel injection system.






# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The engine tappet shaft cover broke because of an internal engine failure.

Engine oil sprayed onto the turbocharger, which is located at the rear of the engine, and started the fire.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences


- 1. Low pressure fuel hoses too close to exhausts. Minimum spacing should be 250 mm.
- 2. Low pressure fuel lines sitting on sharp edges, particularly above exhausts.
- 3. High-pressure fuel line cracks due to vibrations / pulses.
- 4. Failure 'spray zones' oriented towards exhaust pipes.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Turbocharger fires are caused by turbocharger oil seal failure.

The oil seals fail and fire starts on the exhaust side. The fire then spreads to the blowerside via failed oil seals and escapes via the aluminium or rubber air intake pipes.

Risk factors are: hot exhausts and poor oil seal design.



The oil seal on the air-intake side



A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

1.Intercooler air leaks result in low boost. Controllers respond by overfueling.

2.LPG top-up fueling via the air intake will probably cause the exhaust temperature to be high.

3. Turbochargers fail if the exhaust temperature is extreme.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Wheel Bearing Failures**





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



This fire closed one side of the M2 in Sydney during the morning peak hour.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Mechanical failure of the bearings on the front axle is evident.

Note the white edges and crumbling on the brake linings, which witness extreme brake temperature due to dragging brakes because the drum was not centred





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Distressed lubrication on new bearings from axle 2.

Excessive pre-load adjustment caused the early bearing failure.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Bearings wear out, whether they are unitised or open.

Good practice is to have a replacement policy that reflects the nature of the operation. Bearing manufacturers do not estimate bearing life because of variable operating conditions.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Dragging Brakes**





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Dragging brakes cause extreme brake drum temperature.

Drum heat then spreads to the tyre rim via the aluminium wheel rims.

Dragging brakes are caused by bearing failure or brake system defects.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

- 1. Fires due to dragging spring brakes mainly occur on drum brakes.
- 2. Aluminum wheels transmit the heat better than steel rims.
- 3. Dragging disk brakes can cause the wheel seals to fail causing minor oil fires that can spread to the inner tyre.
- 4. Low slung brake actuators are vulnerable to road strike.
- 5. Low-slung spring brake air lines are vulnerable to road strike.
- 6. Poorly maintained spring brake relay valves are vulnerable to leaks.
- 7. Carbon particles (from oil) are generated in unloader-type air compressors on long journeys. These carbon particles clog-up air valves.
- 8. Dragging service brakes rarely occur.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Tyre Rubs**





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



The air suspension deflated en-route and the tyres rubbed on the steel mudguard.

The tyres caught fire at the outside.

This was a car-carrying trailer. The mudguards are sturdy to prevent stones being thrown up and reaching the cars.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Air suspensions will deflate if a supply tube fails.

The driver will see it on the truck but may not see it on a trailer.





# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences



Bracket failures on heavy-duty mudguards.

Rubs on plastic mudguards do not cause fires as the plastic brakes away.







A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

CONFERENCE – 15TH AUGUST, ROYAL RANDWICK, SYDNEY

artsa.com.au/conferences

- 1. Mainly occur on trailers and not trucks because drivers cannot see developing signs.
- 2. Principal cause is deflated air suspensions.
- 3. Secondary cause is deflated inner tyre causing a rub.
- 4. Occasionally tyres rubbing on heavy duty mudguards cause fires.





A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

### **Trailer Mezzanine Fires**






# Heavy Vehicle Fires – Causes and prevention

A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences







A recognised project under the NHVR's *Heavy Vehicle Safety Initiatives* program

artsa.com.au/conferences

# Thanks for Listening !

